# Differential Pressure Gauges Copper Alloy Wetted Parts In-Line Connections Bourdon Tube Series • Type 7X1.12

WIKA Data Sheet 7X1.12

# **Applications**

Measurement of pressure differential or duplex measurement of 2 applied pressures. Suitable for all gaseous and liquid media that will not obstruct the pressure system or attack copper alloy parts.

# **Features**

#### **Sizes**

4" & 6" (100 mm & 160 mm)

#### **Accuracy**

± 1.5% of span

Ranges (All ranges not stocked)

Vacuum 30"Hg

Pressure from 10 psi to 15,000 psi

Scale range must be selected based on the highest static pressure measured. The pressure differential to be indicated should be no less than 1/6 of the full scale range. When ordering please state both the static pressure applied and the differential to be indicated.

#### **Working Range**

Steady: full scale value
Fluctuating: 0.9 x of full scale value
Short time: 1.3 x full scale value

# **Operating Temperature**

Ambient: -4°F to 140°F (-20°C to 60°C)

Media: max. 140°F (+60°C) - 10 pai thru 1000 psi

max. 212°F (+100°C) - 1500 psi thru 15,000 psi

# **Temperature Error**

Additional error when temperature changes from reference temperature of 68°F (20°C)  $\pm 0.4\%$  for every 18°F (10°C) rising or falling. Percentage of span.

# **Weather Protection**

Weather resistant (NEMA 2 / IP 33)

# Connection

Material: copper alloy Lower mount (LM) only 2 x 1/4" or 1/2" NPT

Each side marked with  $\oplus$  or  $\bigcirc$ 



7X12.12 Differential Pressure Gauge

#### **Bourdon Tube**

10 psi to 1,000 psi C-type Material: copper alloy

1,500 psi to 15,000 psi helical type Material: 316 stainless steel

#### Movement

Copper alloy, wearable parts Argentan

#### Dial

White aluminum with black lettering

#### **Pointer**

Material: aluminum 1 black pointer

1 graduated disk indicator with scale ± 50%

of main scale range

#### Case

Black painted steel

#### Window

Flat glass

### **Cover Ring**

Black painted steel screw retained


To determine the effects of temperature and response time in a specific application, contact the factory for an *Application Questionnaire*. The information provided will allow WIKA Technical Support to accurately model your application parameters using state-of-the-art computer simulation techniques.

WIKA Datasheet 7X1.12 • 06/2008

Page 1 of 2



Order Options (min. order may apply)
Duplex gauge with 1 red and 1 black pointer
Subtracting movement (for single-pointer indication)
316 SS wetted parts (Type 731.12)
Liquid filling (4" only) (Type 713.12)
316SS case, ring, and wetted parts (Type 73X.02)
Front flange
Rear flange
Magnetic or inductive alarm contacts (6" size only)



# A\* NOMINAL SIZE

TYPE	WEIGHT	KEY	<b>A</b> *	В	С	E	Т	W	Х
711.12	2.2 lbs.	mm	100	87	82	15.5	1/2"	22	32
4"		in	4	3.43	3.23	0.61	0.87	1.26	
711.12	3.52 lbs.	mm	160	118	86.5	15.5	1/2"	22	32
6"		in	6	4.65	3.41	0.61	0.87	1.26	

Items in **bold** are available from stock (subject to prior sales). For optional items, consult factory for current lead-time.

Options not listed may be available, please consult factory.

Specifications given in this price list represent the state of engineering at the time of printing. Modifications may take place and the specified materials may change without prior notice

WIKA Datasheet 7X1.12 • 06/2008

Page 2 of 2



# **WIKA Instrument Corporation**

1000 Wiegand Boulevard Lawrenceville, GA 30043-5868 Tel: 888-WIKA-USA • 770-513-8200

Fax: 770-338-5118 E-Mail: info@wika.com www.wika.com